

USAEC HQS GTWN

WU WSH

WESTERN UNION INCOMING

BETA
008

TLXA166

WAA179(1747)(1-036496C158002)PD 06/17/74 1720

1974 JUN 17 PM 6 46

ICS IPMVEIB MVN

U.S. ATOMIC ENERGY COMM.
TWX UNIT

02134 TDVE MORRIS IL 126 06-17 225P CDT

PMS MR J. F. O'LEARY, DIRECTOR

DIRECTORATE OF LICENSING

DIRECTORATE OF LICENSING


WUX US ATOMIC ENERGY COMMISSION

WASHINGTON DC 20545

50-249

SUBJECT DPR-25

DRESDEN NUCLEAR POWER STATION UNIT 3.



THIS WILL CONFIRM OUR CONVERSATION WITH F. MAURA OF YOUR OFFICE AT 1315 HOURS THAT DATE CONCERNING A FAILURE TO OPERATE PROPERLY ON MAY 22, 1974 OF MAIN STEAM DRAIN VALVE M03-220-2. WHILE CLOSING THIS VALVE PRIOR TO LOCAL LEAK RATE TESTING THE BREAKER TRIPPED AND REQUIRED RESETTING SEVERAL TIMES BEFORE THE VALVE WOULD FULLY CLOSE THIS PROBLEM WAS NOT NOTED IN THE SHIFT ENGINEERS LOG AT THE TIME AND AS A RESULT THIS REPORT IS SUBMITTED LATE. A 10 DAY LETTER DETAILED THE CORRECTING ACTION IS FORTH COMING IN ACCORDANCE WITH REGULATORY GUIDES 1.16.

B.B. STEPHENSON, SUPERINTENDENT DRESDEN NUCLEAR POWER STATION COMMONWEALTH EDISON COMPANY RTE 1 MORRIS ILLINOIS 60450

NNNN

557P EDT

8310190184 740621
PDR ADOCK 05000249
S PDR

USAEC HQS GTWN

WESTERN UNION INCOMING

50-249

COPY SENT REGION

5526