



Telegram

1974 MAY 15 PH 1:09

VEA222(1401)(1-021392C135)PD 05/15/74 1357

ICS IPMVEIE MVN

05183 TDVE MORRIS IL 102 05-15 1131A CDT

PMS MR JAMES G KEPPLER DIRECTOR DIRECTORATE OF REGULATORY

OPERATIONS REGION 3 WUX US ATOMIC ENERGY

COMMISSION 799 ROOSEVELT RD

GLEN ELLYN IL 60137

SUBJECT: DPR-25 DRESDEN NUCLEUR POWER STATION UNIT 3.

THIS WILL CONFIRM A CONVERSATION WITH F MAURA OF YOUR OFFICE
AT 1045 HOURS THIS DATE CONCERNING MAIN STEAM AREA TEMPERATURE
SWITCHES BEING OUT OF CALIBRATIN 5/15/75 THE CALIBRATION
OF THESE SWITCHES WHICH IS REQUIRED EACH REFUELING OUTAGE
WAS COMPLETED BY THE INSTRUMENT MACHINIST ALL 16 OF THE
SWITCHES WERE FOUND TO HAVE SET POINTS GREATER THAN
THE 200 DEGREE FARENHEIT ALLOWED BY TABLE 3.2.1 OF THE

TECHINIACL SPECIFICATION. THE SWITCHES WERE RECALIBRATED

60427

8310190198 740523
PDR ADDCK 05000249
S PDR



Telegram

TO TRIP AT 180 DEGREE FARENHEIT PLU OR MIUS 5 DEGREE FARENHEIT

B B STEPHENSON

SUPERINTENT DRESDEN

NUCLEUR POWER STA


COMMONWELATH EDISON CO

R R I MORRIS IL

NNNN

MAY 20 1974

1974 MAY 12 6 11:55



UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

7111
TELEPHONE
(312) 858-2660

A. RO Inspection Report No. _____

Transmittal Date : _____

Distribution:
RO Chief, FS&EB
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)
RO Files

Distribution:
RO Chief, FS&EB
RO:HQ (4)
L:D/D for Fuels & Materials
DR Central Files
RO Files

B. RO Inquiry Report No. _____

Transmittal Date : _____

Distribution:
RO Chief, FS&EB
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)
RO Files

Distribution:
RO Chief, FS&EB
RO:HQ
DR Central Files
RO Files

C. Incident Notification From: Commonwealth Edison Co. Docket No. 50-249
(Licensee & Docket No. (or License No.))

Transmittal Date : June 4, 1974

Distribution:
RO Chief, FS&EB
RO:HQ (4)
Licensing (4)
DR Central Files
RO Files

Distribution:
RO Chief, FS&EB
RO:HQ (4)
L:D/D for Fuels & Materials
DR Central Files
RO Files

Handled
50-249