

WESTERN UNION INCOMING

BETH
008

USAEC HQS GTWV

WU WSH

ILKAZ16

44F152(1651)001-035932GP92VPR2)PD 14702774 1649

1974 APR 2 PM 5 31

ICS 1PAMEIA AVN

U.S. ATOMIC ENERGY COMM.
TWX UNIT

1309 TOME MORRIS IL 101 14-02 1114ACDT

PAS XRB J F OLEARY

50-249

DIRECTOR DIRECTORATE OF LICENSING

US ATOMIC ENERGY COMMISSION

WUX

WASHINGTON DC 20545



SUBJECT DFR-25 DRESDEN NUCLEAR POWER STATION UNIT 3
THIS WILL CONFIRM A CONVERSATION WITH F MAURA OF YOUR
OFFICE AT 1040 HOURS THIS DATE CONCERNING A THROUGH WALL
CRACK ON THE 3/4 INCH DRAIN LINE 3-4002B FOR 3B CONTROL ROD
DRIVE WATER FILTER. THE LEAKAGE ASSOCIATED WITH THE FAILURE
WAS MINOR AND CREATED NO AIRBORNE OR CONTAMINATION PROBLEM
THE LEAKING FILTER HAS BEEN ISOLATED AND REPAIR PROCEDURE

HAS BEEN INSTITUTED

B B STEPHENSON

SUPERINTENDENT DRESDEN NUCLEAR POWER STATION

COMMONWEALTH EDISON COMPANY

RURAL ROUTE 1

MORRIS IL

NNNN

8310190256 740611
PDR ADDOCK 05000249
S PDR

USAEC HQS GTWV

APR 1 1020P EDT

WU WSH

WESTERN UNION INCOMING

Handwritten: 50-249

2850

COPY SENT REGION