

50-249

WESTERN UNION INCOMING

Bell 208

1974 MAR 14 PM 9 14

USAEH HNS GTWV

AD KSH

U.S. ATOMIC ENERGY COMM.
TWX UNIT

ILKAZZF WAF179(1829)C1-04002500700020PD 03/14/74 1827

ICS IPVLEU RVN

04231 IDVE MORRIS ILL BY 03-14 300P COT

PM5 MR J.F. O'LEARY DIRECTOR DIRECTORATE OF LICENSING

US ATOMIC ENERGY COMMISSION

WASHINGTON DC 20545

SUBJECT DPR-25 DRESDEN NUCLEAR POWER STATION UNIT 3

THIS WILL CONFIRM A CONVERSATION WITH F. MAURA OF YOUR OFFICE
AT 1400 HOURS THIS DATE CONCERNING A DISCOVERY VIA LOCAL
LEAK RATE TESTING OF EXCESSIVE LEAKAGE PAST FEED WATER

CHECK VALVE 3-220-02A AND 3-220-02A. PREPARATIONS ARE UNDER
WAY TO DISASSEMBLE AND REPAIR THE DEFECTIVE VALVE FURTHER
INFORMATION WILL BE FORWARDED IN THE FORM OF A TEN DAY
LETTER IN ACCORDANCE WITH SECTION 6.8.1.4 OF THE
TECHNICAL SPECIFICATIONS

W P WORDEN SUPERINTENDENT
DRESDEN NUCLEAR POWER STATION
COMMONWEALTH EDISON CO
ROUTE 1 MORRIS ILLINOIS

741PDDT

USAEH HNS GTWV



2256

8310190304 750423
PDR ADDCK 05000249
S PDR

COPY SENT REGION *III*

Incident 50-249