

Vepco

VIRGINIA ELECTRIC AND POWER CO.
Surry Power Station
P.O. Box 315
Surry, Virginia 238

August 25, 1975

Director of Regulatory Operations
230 Peachtree Street, N. W.
Suite 818
Atlanta, Georgia 30303

This is to inform you by telecopy of an Abnormal Occurrence that was noted on August 23, 1975, at Surry Nuclear Power Station.

While Unit 2 was operating at 100% power a leak developed in the Boric Acid Transfer system decreasing the level in the "C" Boric Acid Storage Tank below the minimum specified in section 3.2.B.3 of the Technical Specifications.

E. M. Sweeney
E. M. Sweeney, Jr.
Manager

8403090364 750902
PDR ADOCK 05000281
S PDR

50-240/1