

Vepco

VIRGINIA ELECTRIC AND POWER COMPANY
Surry Power Station
P.O. Box 315
Surry, Virginia 23883

August 25, 1975

Director of Regulatory Operations
230 Peachtree Street, N. W.
Suite 818
Atlanta, Georgia 30303

This is to inform you by telecopy of an Abnormal Occurrence that was noted on August 23, 1975 at Surry Nuclear Power Station.

With Unit 1 operating at approximately 100 per cent power, it was found that one channel of ΔT protection was unconservative due to the failure of a resistance temperature detector.

E. M. Sweeney, Jr.
E. M. Sweeney, Jr.
Manager

8403090382 760202
PDR ADOCK 05000280
S PDR

54-254