

Vepco

VIRGINIA ELECTRIC AND POWER COMPANY
Surry Power Station
P.O. Box 315
Surry, Virginia 23883

August 7, 1975

Director of Regulatory Operations
230 Peachtree Street, N. W.
Suite 818
Atlanta, Georgia 30303

This is to inform you by teletype of an Abnormal Occurrence that was noted on August 7, 1975 at Surry Nuclear Power Station.

The Unit #2 Boron Injection Tank Recirculation Valves, TV-2884A, B, C, were found in the closed position while the unit was at 90% power, 710 MWe.

E. M. Sweeney, Jr.
E. M. Sweeney, Jr.
Manager

8403090398 750818
PDR ADOCK 05000281
S PDR