

Vepco

VIRGINIA ELECTRIC AND POWER COMPANY

Surry Power Station

P.O. Box 313

Surry, Virginia 23883

October 16, 1975

Director of Regulatory Operations  
230 Peachtree Street, N. W.  
Suite 818  
Atlanta, Georgia 30303

This is to inform you by teletype of an Abnormal Occurrence that was noted on October 15, 1975 at Surry Nuclear Power Station.

With Unit #2 operating at 100% power, recirculation of the #2 Bore Injection Tank was interrupted for a period of 15 minutes due to the failure of "B" Boric Acid Transfer Pump Motor. This is a violation of Technical Specification 3.2.3.6.

*E. H. Sweeney, Jr.*  
E. H. Sweeney, Jr.  
Manager

8403090404 751016  
PDR ADOCK 05000281  
S PDR