

Vepco

VE files

VIRGINIA ELECTRIC AND POWER COMPANY
Surry Power Station
P.O. Box 315
Surry, Virginia 23383

July 30, 1975

Director of Regulatory Operations
230 Peachtree Street, N. W.
Suite 818
Atlanta, Georgia 30303

This is to inform you by telecopy of an Abnormal Occurrence that was noted on July 29, 1975 at Surry Nuclear Power Station.

With Unit 2 operating at 100% power, Periodic Test 38.3 indicated the boron concentration in the No. 2 Boron Injection Tank to be 11.4% by weight in lieu of an 11.5% minimum specified in section 3.3.A.3 of the Technical Specifications.

W.P. Stewart
for E. M. Sweeney, Jr.
Station Manager

8403120333 750730
PDR ADOCK 05000281
S PDR

50-281
Inquiry