

MKW POWER SYSTEMS, Inc.



November 12, 1991

Mr. Thomas Murley
Director - Office of Nuclear Reactor Regulation
11555 Rockville Pike
Rockville, MD 20852

Subject: Reportable defect reports 10CFR21-0058 and
10CFR21-0059

Dear Sir:

On 10/11/91 MKW Power Systems notified the USNRC of two
potential reportable defects.

Report number 10CFR21-0058 deals with the camshaft bearing
assembly mounting bolt, EMD PN 188146. Report number
10CFR21-0059 deals with the camshaft locating stud, EMD PN
8034672.

Attached are the follow up reports for these defects.

If there are any questions call Vann Mitchell at
(919)977-2720.

Sincerely,
MKW POWER SYSTEMS, INC.

M. Vann Mitchell

M. Vann Mitchell
Quality Manager

MVM/psp

ATTACHMENT: Report No. 10CFR21-0058
Report No. 10CFR21-0059

9201150220 911112
PDR ADOCK 05000362
S PDR
100100

Post Office Box 1928 • Rocky Mount, North Carolina 27802-1928 • Phone: (919) 977-2720
TWX: (510) 929-0725 • FAX: (919) 446-3830

TE19
111