


**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

March 1, 1984

W3K84-0432  
Q-3-A35.07.97



Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

REFERENCE: LP&L Letter W3K84-0154 dated January 24, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 97  
"Diesel Generator 'B' Turbocharger Failure"  
Second Interim Report

The above referenced letter indicated submittal of the Final Report to the USNRC on March 2, 1984.

At the present time, repairs have been completed on both diesel generators and the 24-hour test run has been performed, however, LP&L is waiting for the official response from Cooper Energy Services as to the cause of the malfunctions, which is now scheduled to be completed by late March 1984.

The Final Report will be submitted to the USNRC on April 6, 1984.

Very truly yours,

*T. F. Gerrets*  
T. F. Gerrets

Corporate Quality Assurance Manager

TFG:CNH:SSTG

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8403130339 840301  
PDR ADDCK 05000382  
S PDR

*Is 27*  
*1/0*

Mr. John T. Collins  
March 1, 1984  
W3K84-0432  
Page 2

cc: Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. E. L. Blake  
Shaw, Pittman, Potts, & Trowbridge  
1800 M Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339