

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

March 2, 1984
ANPP-28996-BSK/TRB

U. S. Nuclear Regulatory Commission
Region V
Creekside Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director
Division of Resident
Reactor Projects and Engineering Programs


Subject: Interim Report - DER 84-07
A 50.55(e) Reportable Deficiency Relating to Borg Warner
Valves Stem Extensions And The Failure to Provide Corrective
Action As Stated In DER 80-21
File: 84-019-026; D.4.33.2

Reference: Telephone Conversation between P. Narbut and T. Bradish on
February 9, 1984.

Dear Sir:

The NRC was notified of a reportable deficiency in the referenced telephone conversation. Due to the extensive investigation and evaluation required, an Interim Report is attached. It is now expected that this information will be finalized by April 16, 1984, at which time a complete report will be submitted.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President, Nuclear
ANPP Project Director

EEVB/TRB:db
Attachment

cc: See Page Two

8403200160 840302
PDR ADOCK 05000529
S PDR

1E-27

Mr. T. W. Bishop
DER 84-07
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
W. E. Ide
D. B. Fasnacht
A. C. Rogers
B. S. Kaplan
L. A. Souza
J. Vorees
J. R. Bynum
P. P. Klute
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. D. Foster
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli
S. R. Frost
J. Self
D. Canady

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339

INTERIM REPORT - DER 84-07
REPORTABLE DEFICIENCY
ARIZONA PUBLIC SERVICE COMPANY (APS)
PVNGS UNIT 2 & 3

I. Description of Problem

NCRs NA-1251 and NA-1252 have been issued to identify a nonconformance which resulted from NCR PX-1412, being superseded. NCR PX-1412 was applicable to Units 1, 2 & 3. However, NCR NA-372 which superseded NCR PX-1412 only addressed Unit 1 valves. DER 80-21 was originally written for NCR PX-1412.

The NCRs and the DER 80-21 were closed prior to any repair to Units 2 and 3 valves.

Units 2 and 3 valves in question are indeterminate.

II. Approach to and Status of Proposed Resolution

Bechtel Engineering is investigating the Units 2 and 3 correction action required.

III. Projected Completion of Corrective Action and Submittal of the Final Report

Evaluation of this condition and submittal of the Final Report is Forecast to be completed by April 16, 1984.