

# LICENSEE EVENT REPORT

50-285/76-31

CONTROL BLOCK 1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME 01 N E F C S 1 14														LICENSE NUMBER 0 0 - 0 0 0 0 0 0 - 0 0 25											LICENSE TYPE 4 1 1 1 1 30					EVENT TYPE 0 3 31 32	
01 CONT 7 8		CATEGORY 57 58		REPORT TYPE 59		REPORT SOURCE 60		DOCKET NUMBER 0 5 0 - 0 2 8 5 68								EVENT DATE 0 9 0 8 7 6 74					REPORT DATE 0 9 2 0 7 6 80										

## EVENT DESCRIPTION

02 A spent fuel pool rack was transferred from the cask decon area to a location just north of the spent fuel pool to provide additional room for rack disposal. Contrary to Technical Specification 2.11, a portion of the rack passed over the spent fuel. Violation was recognized on September 8, 1976. (LER 50-285/76-31)																																																																															
03																																																																															
04																																																																															
05																																																																															
06																																																																															

SYSTEM CODE 07 F B 7 8 9 10		CAUSE CODE A 11		COMPONENT CODE Z Z Z Z Z Z 17					PRIME COMPONENT SUPPLIER Z 43		COMPONENT MANUFACTURER Z 9 9 9 9 47					VIOLATION Y 48	
--------------------------------	--	--------------------	--	----------------------------------	--	--	--	--	----------------------------------	--	--	--	--	--	--	-------------------	--

## CAUSE DESCRIPTION

08 Supervisor in charge of operation misinterpreted the intent of the Technical Specification.																																																																															
09																																																																															
10																																																																															

FACILITY STATUS 11 E 7 8 9		% POWER 0 9 8 10 12		OTHER STATUS NA 13		METHOD OF DISCOVERY D 44 45		DISCOVERY DESCRIPTION Reconstructed sequence of transfer 80											
FORM OF ACTIVITY RELEASED 12 Z 7 8 9		CONTENT OF RELEASE Z 10 11		AMOUNT OF ACTIVITY NA 44		LOCATION OF RELEASE NA 45													

## PERSONNEL EXPOSURES

NUMBER 13 0 0 0 7 8 9 11		TYPE Z 12		DESCRIPTION NA 13	
-----------------------------	--	--------------	--	----------------------	--

## PERSONNEL INJURIES

NUMBER 14 0 0 0 7 8 9 11		DESCRIPTION NA 12	
-----------------------------	--	----------------------	--

## OFFSITE CONSEQUENCES

15 NA 7 8 9																																																																															
-------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

## LOSS OR DAMAGE TO FACILITY

TYPE 16 Z 7 8 9 10		DESCRIPTION NA	
-----------------------	--	-------------------	--

## PUBLICITY

17 NA 7 8 9																																																																															
-------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

## ADDITIONAL FACTORS

18 See Attachments 1, 2 and 3 7 8 9																																																																															
-------------------------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

19 7 8 9																																																																															
----------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

NAME: S. M. Moyers

PHONE: 402-426-4011

ATTACHMENT NO. 1

Safety Analysis

This specification was developed to prevent the possibility of dropping a load in the spent fuel. The analysis of this event is covered in the FSAR Section 14.18.

ATTACHMENT NO. 2

Corrective Action

The supervisor involved in this incident was reinstructed as to the meaning of this technical specification. He had recently completed a study guide and passed a written examination on this subject, consequently, this material was reviewed to assure that the point of confusion in the interpretation was specifically addressed on the quiz to identify and prevent this misinterpretation in the future.

LER 50-285/76-31  
Page Four

ATTACHMENT NO. 3

Failure Data

This is the first time an event of this type has occurred.



# Omaha Public Power District

1623 HARNEY ■ OMAHA, NEBRASKA 68102 ■ TELEPHONE 536-4000 AREA CODE 402

September 21, 1976  
FC-281-76

Mr. E. Morris Howard  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive  
Suite 1000  
Arlington, TX 76012



Dear Mr. Howard:

Reference: Fort Calhoun Station Unit No. 1  
Docket No. 50-285

In accordance with the Fort Calhoun Station's Technical Specifications, the Omaha Public Power District, as holder of facility operating license DPR-40, submits three copies of the following licensee event report 50-285/76-31 to satisfy the requirements of Regulatory Guide 1.16.

Sincerely,

W. C. Jones  
Section Manager  
Operations

WCJ/WDD:rge

Enclosures

cc: Director, Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555 (3)

Director, Office of Inspection and  
Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555 (30)

Mr. L. C. Shalla  
SARC Chairman  
PRC Chairman  
Fort Calhoun File (2)

9750

COPY SENT REGION