



PECO ENERGY

Robert W. Boyce
Plant Manager
Limerick Generating Station

PECO Energy Company
Limerick Generating Station
PO Box 2300
Sanatoga, PA 19464-0920
215 327 1200 Ext. 2000

10CFR50.73

August 18, 1995
Docket No. 50-352
License No. NPF-39

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

SUBJECT: Licensee Event Report
Limerick Generating Station - Unit 1

This LER reports an event where the plant was in non-compliance with the requirements of Facility Operating License NPF-39, Condition 2.C.1 in that the Unit 1 maximum power level of 100% was exceeded by approximately 3.4%. The power transient was caused by an unanticipated response of the 1B reactor recirculation pump following a decrease speed signal.

Reference:	Docket No. 50-352
Report Number:	1-95-003
Revision Number:	00
Event Date:	July 19, 1995
Report Date:	August 18, 1995
Facility:	Limerick Generating Station P.O. Box 2300, Sanatoga, PA 19464-2300

This LER is being submitted pursuant to the requirements of License Condition 2.F, which requires a 30-day written followup report.

Very truly yours,

cc: T. T. Martin, Administrator Region I, USNRC
N. S. Perry, USNRC Senior Resident Inspector, LGS

220070

9508230003 950818
PDR ADOCK 05000352
S PDR

JE221