




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 386-2345

March 9, 1984

W3K84-0499
Q-3-A35.07.78



Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 7601

REFERENCE: LP&L letter W3K84-0208 dated January 31, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 78
"American Bridge Structural Steel Deficiencies"
Seventh Interim Report

The above referenced letter indicated submittal of a Final Report to the USNRC on March 9, 1984.

At the present time, corrective action remains on 2 nonconformance reports and is scheduled to be completed in late March, 1984.

A Final Report will be submitted to the USNRC on April 6, 1984.

Very truly yours,

T. F. Gerrets
T. F. Gerrets

Corporate Quality Assurance Manager

TFG:CNH:VBK

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8403270206 840309
PDR ADOCK 05000382
S PDR

IE-27

110

Mr. John T. Collins

March 9, 1984

W3K84-0499

Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake
Shaw, Pittman, Potts, & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130