

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE (717) 542-3759

JEZUS



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

March 20, 1984

Dr. Thomas E. Murley
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 83-153/03X-1
ER 100450 FILE 841-23
PLA-2144

Docket No. 50-387
License No. NPF-14

Dear Dr. Murley:

1 Attached is the update to LER 83-153/03L-0. The event was reportable per Technical Specification 6.9.1.9.b, in that Reactor Core Isolation Cooling (RCIC) instruments at the Remote Shutdown Panel (RSP) were de-energized due to a blown fuse. The fuse has been replaced with a 10 amp. slow blow fuse. System operation has been satisfactory. Similar occurrences were reported in LER 83-36/03X-1. No further actions or LER updates are planned.

H.W. Keiser
Superintendent of Plant-Susquehanna

LAK/pjg

cc: Mr. R.H. Jacobs
Senior Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 52
Shickshinny, PA 18655

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

IE22
11