

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Joseph M. Farley - Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 4 8	PAGE (3) 1 OF 0 1
--	--------------------------------------	----------------------

TITLE (4)
Fire Barrier Penetration Not Properly Sealed

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)							
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)						
0	3	0	2	8	4	8	4	0	0	8	0	0	0	3	6	4
0	3	0	2	8	4	8	4	0	0	8	0	0	0	3	6	4

OPERATING MODE (9) 6	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)															
POWER LEVEL (10) 0 0 0	20.402(b)	20.405(a)(1)(i)	20.405(a)(1)(ii)	20.405(a)(1)(iii)	20.405(a)(1)(iv)	20.405(a)(1)(v)	20.405(a)(2)(i)	20.405(a)(2)(ii)	20.405(a)(2)(iii)	20.405(a)(2)(iv)	20.405(a)(2)(v)	20.405(a)(2)(vi)	20.405(a)(2)(vii)	20.405(a)(2)(viii)	20.405(a)(2)(ix)	20.405(a)(2)(x)
	20.402(b)	20.405(a)(1)(i)	20.405(a)(1)(ii)	20.405(a)(1)(iii)	20.405(a)(1)(iv)	20.405(a)(1)(v)	20.405(a)(2)(i)	20.405(a)(2)(ii)	20.405(a)(2)(iii)	20.405(a)(2)(iv)	20.405(a)(2)(v)	20.405(a)(2)(vi)	20.405(a)(2)(vii)	20.405(a)(2)(viii)	20.405(a)(2)(ix)	20.405(a)(2)(x)
	20.402(b)	20.405(a)(1)(i)	20.405(a)(1)(ii)	20.405(a)(1)(iii)	20.405(a)(1)(iv)	20.405(a)(1)(v)	20.405(a)(2)(i)	20.405(a)(2)(ii)	20.405(a)(2)(iii)	20.405(a)(2)(iv)	20.405(a)(2)(v)	20.405(a)(2)(vi)	20.405(a)(2)(vii)	20.405(a)(2)(viii)	20.405(a)(2)(ix)	20.405(a)(2)(x)
	20.402(b)	20.405(a)(1)(i)	20.405(a)(1)(ii)	20.405(a)(1)(iii)	20.405(a)(1)(iv)	20.405(a)(1)(v)	20.405(a)(2)(i)	20.405(a)(2)(ii)	20.405(a)(2)(iii)	20.405(a)(2)(iv)	20.405(a)(2)(v)	20.405(a)(2)(vi)	20.405(a)(2)(vii)	20.405(a)(2)(viii)	20.405(a)(2)(ix)	20.405(a)(2)(x)
	20.402(b)	20.405(a)(1)(i)	20.405(a)(1)(ii)	20.405(a)(1)(iii)	20.405(a)(1)(iv)	20.405(a)(1)(v)	20.405(a)(2)(i)	20.405(a)(2)(ii)	20.405(a)(2)(iii)	20.405(a)(2)(iv)	20.405(a)(2)(v)	20.405(a)(2)(vi)	20.405(a)(2)(vii)	20.405(a)(2)(viii)	20.405(a)(2)(ix)	20.405(a)(2)(x)
73.71(b)																
73.71(c)																
X OTHER (Specify in Abstract below and in Text, NRC Form 366A)																
Special Report																

LICENSEE CONTACT FOR THIS LER (12)														
NAME W. G. Hairston, III										TELEPHONE NUMBER 2 0 5 8 9 9 1 - 5 1 5 6				

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)														
CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)										EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE) X NO														

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

At 0915 on 3-2-84, it was determined that the control room fire barrier penetration for the NRC red phone cable was not properly sealed. Investigation revealed that the penetration had been opened on 2-2-84, under PCN B81-1003, to install the NRC red phone on the operators desk. Upon completion of the work, the penetration was not properly sealed.

Since the control room is manned continuously, a firewatch was maintained during the time that the penetration was non-functional. The penetration was properly sealed and returned to functional status at 1455 on 3-3-84. In addition, the electrical maintenance personnel involved will be reinstructed on the use of FNP-0-MP-35.1 (Installation of Penetration Seals).

8404030202 840329
PDR ADOCK 05000348
S PDR

Mailing Address

Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Alabama 35291
Telephone 205 783-6081

F. L. Clayton, Jr.
Senior Vice President
Flintridge Building



Alabama Power

the southern electric system

March 29, 1984

Docket No. 348


Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Sir:

Joseph M. Farley Nuclear Plant, Unit 1, Licensee Event Report No. LER 84-008-00 is forwarded in accordance with Technical Specification 3.7.12, action statement a, to provide 30 day written notification of this occurrence.

If you have any questions, please advise.


Yours very truly,


F. L. Clayton, Jr.

FLCJr/KWM:sam

Enclosures

xc: IE, Region II


IE-22
11

• • • bc: Mr. J. M. Farley
Mr. W. O. Whitt
Mr. S. E. Bradley
Mr. W. H. Bradford
Mr. R. P. McDonald
Mr. H. O. Thrash
Mr. O. D. Kingsley, Jr.
Mr. J. W. McGowan
Mr. D. S. Mask
Mr. W. G. Hairston, III
Mr. L. S. Williams
Mr. W. G. Ware
Mr. T. H. Nesbit
INPO Records Center
File: A-3.1/F-6