




Public Service Company of Colorado

16805 WCR 19 1/2, Platteville, Colorado 80651

March 28, 1984
Fort St. Vrain
Unit #1
P-84095

50-267



Mr. John T. Collins, Regional Administrator
Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76011

REFERENCE: Facility Operating License
No. DPR-34

Docket No. 50-267

Dear Mr. Collins:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/80-30, and Reportable Occurrence Report No. 50-267/81-068, Revised Finals, submitted per the requirements of Technical Specification AC 7.5.2(b)2.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/80-30, and Reportable Occurrence No. 50-267/81-068.

Very truly yours,

Don Warembourg

Don Warembourg
Manager, Nuclear Production

DWW/djm

Enclosure

cc: Director, MIPC

8404090140 840328
PDR ADOCK 05000267
S PDR

H005
11