

# SNUPPS

Standardized Nuclear Unit  
Power Plant System

5 Choke Cherry Road  
Rockville, Maryland 20850  
(301) 869-8010

Nicholas A. Petrick  
Executive Director

April 9, 1984

SLNRC 84-0062 FILE: 0278  
SUBJ: Instrument Error for  
Containment Pressure  
Setpoints

Mr. Harold R. Denton, Director  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555


Docket Nos. STN 50-482 and STN 50-483

- References: 1. NRC Letter (B. Youngblood) to Union Electric (D. Schnell)  
and Kansas Gas and Electric (G. Koester) dated April 2,  
1984  
2. SLNRC 84-0050, dated March 23, 1984, Response to NRC  
Questions on Setpoint Methodology for SNUPPS

Dear Mr. Denton:

Reference 1 requested additional justification for instrument channel errors greater than 1 psi for the containment pressure instruments at the SNUPPS plants - Callaway Plant Unit No. 1 and Wolf Creek Generating Station Unit No. 1. Reference 2 provided the requested information for the Callaway Plant. Refer to item 22 of Table 3-16, "Reactor Protection System/Engineered Safety Features Actuation System Channel Error Allowances". A similar table, with Wolf Creek - specific data, will be provided at a later date.

Very truly yours,



Nicholas A. Petrick

MHF/nld9a30

cc: G. L. Koester	KGE	J. Neisler/B. Little	USNRC/CAL
D. T. McPhee	KCPL	W. Schum/A. Smith	USNRC/WC
D. F. Schnell	UE	J. Konklin	USNRC/RIII

8404130164 840409  
PDR ADOCK 05000482  
PDR

Boo1  
1/0