




**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 386-2345

June 29, 1984

W3K84-1505  
Q-3-A35.07.37  
Q-3-A35.07.80  
Q-3-A35.07.93

Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiencies Nos. 37, 80, and 93  
Extension Request

In accordance with previous commitments, the Final Report for the listed Significant Construction Deficiencies were scheduled to be provided to the USNRC in early July 1984. However due to recent changes the Final Reports for the subject SCD's will be submitted to the USNRC, after Post Core Hot Functional Testing, as indicated below.

SCD 37, "Temperature Detectors (RTD's) Failure" September 7, 1984.  
SCD 80, "Unsatisfactory Stroking of EFW Pump Turbine Steam Supply Shutoff Valves" September 7, 1984.  
SCD 93, "Charging and Letdown Containment Isolation Valve Deficiency" September 7, 1984.

Very truly yours,

T. F. Gerrets  
Corporate Quality Assurance Manager

TFG:CNH:VBR

8407130168 840629  
PDR ADOCK 05000382  
S PDR

119  
IE-27

Mr. John T. Collins

June 29, 1984

W3K84-1505

Page 2

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. E. L. Blake  
Shaw, Pittman, Potts & Trowbridge  
1800 M Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

Mr. W. A. Cross  
7910 Woodmont Avenue  
Suite 1200  
Bethesda, Maryland 20814