

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME: 01 N Y N M P 1										LICENSE NUMBER: 15 - - - - - - - - -										LICENSE TYPE: 4 1 1 1 1					EVENT TYPE: 0 4	
CATEGORY: 01 CONT		REPORT TYPE: M I		REPORT SOURCE: L		DOCKET NUMBER: 0 5 0 - 0 2 2 0					EVENT DATE: 0 4 2 7 7 6					REPORT DATE: 0 4 2 8 7 6										

EVENT DESCRIPTION

02	During routine impingement sampling by contractor personnel on 04/26/76 - 04/27/76	80
03	the numbers of fish being impinged on the traveling screens exceeded ETS limit of	80
04	20,000/24 hr. (Sect. 3.1.2 a 2).	80
05	04/26-27/76 - 27,922 (94% alewives)	80
06	RO 76-16	80

SYSTEM CODE: H F		CAUSE CODE: F		COMPONENT CODE: Z Z Z Z Z Z					PRIME COMPONENT SUPPLIER: Z		COMPONENT MANUFACTURER: Z 9 9 9					VIOLATION: -	
--	--	---	--	---	--	--	--	--	---	--	---	--	--	--	--	--	--

CAUSE DESCRIPTION

08	There was no apparent cause for this occurrence related to changes in plant operation.	80
09	The principle species impinged alewives and rainbow smelt migrate inshore for spawn-	80
10	ing at this time of year.	80

FACILITY STATUS: F		% POWER: 0 7 8		OTHER STATUS: N/A		METHOD OF DISCOVERY: a		DISCOVERY DESCRIPTION:	
FORM OF ACTIVITY RELEASED: Z		CONTENT OF RELEASE: Z		AMOUNT OF ACTIVITY: N/A		LOCATION OF RELEASE: N/A			

PERSONNEL EXPOSURES

NUMBER: 0 0 0		TYPE: Z		DESCRIPTION: N/A	
---	--	---	--	--	--

PERSONNEL INJURIES

NUMBER: 0 0 0		DESCRIPTION: N/A	
---	--	--	--

OFF-SITE CONSEQUENCES probable

NONE	
------	--

LOSS OR DAMAGE TO FACILITY

TYPE: Z		DESCRIPTION: N/A	
---	--	--	--

PUBLICITY

N/A		8302170480 760420 PDR ADOCK 05000220 S PDR	
-----	--	--	--

ADDITIONAL FACTORS

18	Contractor personnel remained onsite to monitor impingement until numbers fell below	80
19	20,000/24 hr. as per ETS.	80