

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME 01 N Y N M P 1	LICENSE NUMBER 	LICENSE TYPE 4 1 1 1 1	EVENT TYPE 0 1
---	---	---	---

CON'T 01	CATEGORY M I	REPORT TYPE L	REPORT SOURCE L	DOCKET NUMBER 0 5 0 - 0 2 2 0	EVENT DATE 0 2 1 0 7 6	REPORT DATE 0 3 0 3 7 6
---	---	--	--	--	---	--

EVENT DESCRIPTION

02 During Routine Surveillance, RO15C, a refuel platform high range monitor/calibration
03 calibration indicated a response of 350 mr/hr rather than 800 mr/hr. No irradiated
04 fuel movement or cast handling was taking place. Therefore, no hazard was presented
05 to the General Public.
06 RO 76-05

SYSTEM CODE B A	CAUSE CODE D	COMPONENT CODE I N S T R U	PRIME COMPONENT SUPPLIER W	COMPONENT MANUFACTURER G 0 8 0	VIOLATION N
--	---	---	---	---	--

CAUSE DESCRIPTION

08 Detector has failed and has been replaced.
09 Part Number - 5481718
10

FACILITY STATUS E	% POWER 0 9 0	OTHER STATUS 	METHOD OF DISCOVERY b	DISCOVERY DESCRIPTION
--	--	---	--	--

FORM OF ACTIVITY RELEASED z	CONTENT OF RELEASE z	AMOUNT OF ACTIVITY N/A	LOCATION OF RELEASE
--	---	---------------------------	--

PERSONNEL EXPOSURES

NUMBER 0 0 0	TYPE z	DESCRIPTION N/A
---	---	--------------------

PERSONNEL INJURIES

NUMBER 0 0 0	DESCRIPTION N/A
---	--------------------

PROBABLE CONSEQUENCES Probable
NONE

15 80

LOSS OR DAMAGE TO FACILITY

TYPE z	DESCRIPTION N/A
---	--------------------

16 80

PUBLICITY 8302170564 760303
PDR ADOCK 05000220
S PDR

17 NONE 80

ADDITIONAL FACTORS

18 NONE 80

19 80

19 80

NAME: T. Dente

PHONE: 315-343-2110