

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

01 N Y N M P 1 7 8 9 14
 15 25 26 30 31 32
 01 CON'T CATEGORY M I 57 58
 REPORT TYPE T 59
 REPORT SOURCE L 60
 DOCKET NUMBER 0 5 0 - 0 2 2 0 61 68
 EVENT DATE 0 4 2 8 7 6 69 74
 REPORT DATE 0 5 0 4 7 6 75 81

EVENT	DESCRIPTION
1	...
2	...
3	...
4	...
5	...
6	...
7	...
8	...
9	...
10	...
11	...
12	...
13	...
14	...
15	...
16	...
17	...
18	...
19	...
20	...
21	...
22	...
23	...
24	...
25	...
26	...
27	...
28	...
29	...
30	...
31	...
32	...
33	...
34	...
35	...
36	...
37	...
38	...
39	...
40	...
41	...
42	...
43	...
44	...
45	...
46	...
47	...
48	...
49	...
50	...
51	...
52	...
53	...
54	...
55	...
56	...
57	...
58	...
59	...
60	...
61	...
62	...
63	...
64	...
65	...
66	...
67	...
68	...
69	...
70	...
71	...
72	...
73	...
74	...
75	...
76	...
77	...
78	...
79	...
80	...
81	...
82	...
83	...
84	...
85	...
86	...
87	...
88	...
89	...
90	...
91	...
92	...
93	...
94	...
95	...
96	...
97	...
98	...
99	...
100	...

02	During routine impingement sampling by contractor personnel (4/28-29/76) it was	
7	8	9
03	found that the numbers of fish being impinged on the traveling screens exceeded	80
7	8	9
04	the ETS limit of 20,000/24 hr. period as per Sect. 3.1.2.a2	80
7	8	9
05	(See Attachment)	80
7	8	9
06		80
7	8	9
		RO 76-17

SYSTEM CODE		CAUSE CODE		COMPONENT CODE						PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
0	7	H	F	Z	Z	Z	Z	Z	Z	Z	Z	9	9	9	-		
7	8	9	10	11	12					17	43	44			47	48	

CAUSE DESCRIPTION

09 | There was no apparent cause for this occurrence that could be directly related to
7 8 9 |
09 | changes in plant operations. The principal species impinged, alewives, rainbow
7 8 9 | 80
10 | smelt migrate inshore annually at this time of year.
7 8 9 | 80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		80
1	1	F	0	8	7	N/A	a			
7	8	9	10	11	12	13	44	45	46	80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
1	2	3	N/A	N/A

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	3	0	0	0	N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	N/A

OFFSITE CONSEQUENCES probable

1	5	NONE
7	8	9

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
15	2		N/A
7	8	9	10

PUBLCITY		B302180027 760528		80
17	N/A	PDR ADOCK 05000220		
		PDR		

ADDITIONAL FACTORS

1a Contractor personnel remained on Site until numbers fell below 20,000/24 hr. as

per ETS. This occurred on 5/01/76.

NAME: M. Hedrick

PHONE 343-2110 Ext. 1310

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

May 7, 1976



Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa. 29406

RE: Docket No. 50-220

Dear Mr. O'Reilly:

In accordance with Nine Mile Point Nuclear Station Unit #1 Environmental Technical Specification 5.6.3.1, we hereby submit Licensee Event Report 76-17.

This report was completed within the intent of the Licensee Event Report Instruction Booklet OOE-SS-001, dated October 1974, revised December 24, 1974. Due to the minimal significance category of the report, no supplemental report is included.

Very truly yours,

Original Signed by R.R. Schneider

R.R. Schneider
Vice President
Electric Operations

MCH/aih

Enc. 2 copies

cc: (20 copies) Director, Office of Inspection
and Enforcement

(2 copies) Director, Office of Management Information
and Program Control