

ILLINOIS POWER COMPANY



0982-L
U-10168

CLINTON POWER STATION, P.O. BOX 678, CLINTON, ILLINOIS 61727

June 25, 1984

Docket No. 50-461

Mr. James G. Keppler
Regional Administrator
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Systematic Assessment of Licensee Performance,
October 1, 1982 through February 29, 1984

Dear Mr. Keppler:

Illinois Power Company has reviewed the preliminary Inspection Report 50-461/84-03 covering the Systematic Assessment of Licensee Performance for Clinton Power Station. Illinois Power Company is pleased with the results of the Systematic Assessment of Licensee Performance and has no comment on the specific conclusions reached by the Board. The reference to untimely management responsiveness is of concern, and Illinois Power Company will continue its efforts to raise management responsiveness to a more acceptable level.

This SALP has provided both confirmation of those activities being performed well and criticism of those activities that would benefit from additional management attention. Illinois Power Company will continue to support a strong, effective quality assurance program which will ensure quality construction, testing, and operation.

Sincerely yours,

D. F. Hall,
Vice President

JRS/cbs (NRC)

cc: Director, Office of I&E, US NRC, Washington, DC 20555
NRC Resident Office
Illinois Department of Nuclear Safety

JUN 27 1984

8407190355 840625
PDR ADOCK 05000461
PDR
Q