

CONTROL BLOCK:

1					6

LICENSEE
NAME

LICENSE NUMBER

LICENSE
TYPE

EVENT
TYPE

01	I	L	D	R	S	2	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3	
7	8	9				14	15											25	26				30	31	32

01	CONT			L	L	0500-0237	041176	051176																	
7	8			57	58	59	60	61				68	69				74	75							80

CATEGORY
 REPORT TYPE
 REPORT SOURCE
 DOCKET NUMBER
 EVENT DATE
 REPORT DATE

02 DURING NORMAL OPERATION OF THE ECCS JOCKEY PUMP 1401-2A, SMOKE WAS FOUND
7 8 9 80

03 TO BE EMANATING FROM THE PUMP'S CONTROL FEEDER BREAKER AT MCC 28-1. THE
7 8 9 80

04 PUMP MOTOR. BREAKER CONTACTS, AND WIRING WERE NOT DAMAGED; HOWEVER, AN OPENED CON-
7 8 9 80

05 TACTOR COIL IN THE CIRCUIT HAD TO BE REPLACED. THE REDUNDANT SYSTEM, THE ECCS
7 8 9 80

06 FILL VALVE FROM THE CST, WAS OPERABLE. THIS IS NOT A REPETITIVE EVENT. (50-237/1976-22)
7 8 9 80

SYSTEM
CODECAUSE
CODE

COMPONENT CODE

PRIME
COMPONENT
SUPPLIER

COMPONENT
MANUFACTURER

VIOLATION

07 S F E C K T B R K N G O 8 O N

7 8 9 10 11 12 13 14 15 16 17 43 44 45 46 47 48

08	THE EVENT WAS CAUSED BY A BURNED-OUT CONTACTOR COIL, THERMAL FATIGUE AND	80
09	GENERAL AGING APPARENTLY CAUSED THE COIL TO FAIL. THE AFFECTED BREAKER IS A GEN-	80
10	CRAI ELECTRIC 480 V A.C. CIRCUIT BREAKER, TYPE FVNR, SIZE 2.	80

FACILITY
STATUS

% POWER

OTHER STATUS

METHOD OF DISCOVERY

DISCOVERY DESCRIPTION

11 7 8 H 9 10 11 12 NA 13 44 A 45 46 NA

FORM OF
ACTIVITY
RELEASED

CONTENT
OF RELEASE

AMOUNT OF ACTIVITY

LOCATION OF RELEASE

12		9		10		11		44		45	
RELEASED		RELEASED		RELEASED		AMOUNT OF ACTIVITY		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
Z		Z		Z		NA		NA		NA	

NUMBER				TYPE	DESCRIPTION
13	0	0	0	R	NA

NUMBER				DESCRIPTION	
1	4	0	0	0	NA

15	NA
----	----

TYPE		DESCRIPTION
16	2	NA

17	NA
----	----

18 | NA

8303310090 760511
PDR ADCK 05000237
S PDR

NAME: K. D. LEITZELL

PHONE: EXT. 422



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

BBS Ltr, #362-76

May 10, 1976

Mr. James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Enclosed please find Reportable Occurrence number 50-27/1976-22.
This report is being submitted to your office in accordance with the
Dresden Nuclear Power Station Technical Specifications, Section 6.6.B.

B. B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS:smp

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

4972

COPY SENT REGION III