

TO: Regional Director
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

MAIL: 1-27-110
Telecopies Date 3-25-76
or
Telegraphed GE 8:15A
DC
By XC

cc:
Director
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

SUBJECT: DPR-19, Dresden Nuclear Power Station, Unit 2.

This will confirm a conversation with Phil Johnson of
your office at 1530 hrs this date concerning the wall
crack indication on the HPCI steam
supply line safe end. Found during
refueling outage ISI inspection.
The crack is in the heat affected
zone of the safe end weld.

8303310170 760325
PDR ADOCK 05000237
S PDR

3-25-76 8:20 a.m. L.S.

To Call:

GE - 7-858-2660x16
DC - 9-1-301-492-7617 (auto)
WU - 815-942-4449/4321

Station Dist: Originator (copy)
Incident File (copy)

E. B. Stephenson, Superintendent
Dresden Nuclear Power Station
Commonwealth Edison Company
R.R. #1
Morris, IL 60450

Telephone: 815-942-2920/2921x212

Rev. 12-75

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLFN ELLYN, ILLINOIS 60137

Incident Notification From: Commonwealth Edison Company 50-237
(Licensee & Docket No. (or License No.))

Transmittal Date: April 14, 1976 Dresden Station Unit #2

Distribution:

IE Chief, FOSB
IE Chief, FC&EB
IE:HQ(4)
Licensing(4)
DR Central Files
IE Files

Distribution:

IE Chief, FOSB
IE Chief, FC&EB
IE:HQ(4)
L:D/D for Fuels & Materials
DR Central Files
IE Files