

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 I L D R S 2										LICENSE NUMBER: 00 0 0 0 0 0 0 0 0 0										LICENSE TYPE: 4 1 1 1 1					EVENT TYPE: 0 3																								
CATEGORY: 01 CONT										REPORT TYPE: L					REPORT SOURCE: L					DOCKET NUMBER: 05 0 0 2 3 7										EVENT DATE: 03 2 4 7 6										REPORT DATE: 04 2 3 7 6									

EVENT DESCRIPTION

02 DURING A ROUTINE INSPECTION OF THE ISOLATION CONDENSER PIPEWAY SNUBBERS, SNUBBERS

03 #2 & #3 APPEARED TO BE IN AN INOPERABLE CONDITION DUE TO LOSS OF FLUID.

04 BOTH SNUBBERS WERE REMOVED AND BENCH-TESTED TO DETERMINE THE CAUSE

05 OF FAILURE. SHOCK SUPPRESSOR LEAKAGE IS A REPETITIVE OCCURRENCE.

06 (50-237/1976-15)

SYSTEM CODE: 07 C E					CAUSE CODE: E					COMPONENT CODE: H A N G E R					PRIME COMPONENT SUPPLIER: N					COMPONENT MANUFACTURER: G 2 5 5					VIOLATION: Y				
---	--	--	--	--	---	--	--	--	--	---	--	--	--	--	---	--	--	--	--	---	--	--	--	--	--	--	--	--	--

CAUSE DESCRIPTION

08 BENCH-TESTING OF THE TWO SNUBBERS REVEALED THAT DESPITE SOME FLUID

09 LEAKAGE THROUGH SHAFT SEALS AND LOOSE CONNECTOR FITTINGS, BOTH SNUBBERS DID

10 IN FACT LOCK UP PROPERLY DURING A TEST INITIATION, CORRECTIVE ACTION WAS TO

(CONTINUED BELOW)

FACILITY STATUS: 11 H					% POWER: 00 0 0					OTHER STATUS: NA					METHOD OF DISCOVERY: B					DISCOVERY DESCRIPTION: NA				
FORM OF ACTIVITY RELEASED: 12 Z					CONTENT OF RELEASE: Z					AMOUNT OF ACTIVITY: NA					LOCATION OF RELEASE: NA									

PERSONNEL EXPOSURES

NUMBER: 13 0 0 0					TYPE: Z					DESCRIPTION: NA				
--	--	--	--	--	---	--	--	--	--	---	--	--	--	--

PERSONNEL INJURIES

NUMBER: 14 0 0 0					DESCRIPTION: NA				
--	--	--	--	--	---	--	--	--	--

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE: 16 Z					DESCRIPTION: NA				
--	--	--	--	--	---	--	--	--	--

PUBLICITY

17 NA

8303310233 760-23
PDR ADOCK 05000237
S PDR

ADDITIONAL FACTORS CAUSE DESCRIPTION (CONTINUED)

18 REPLACE THE CONNECTOR FITTINGS, SHAFT "O" RINGS, AND WIPERS ON

19 BOTH SNUBBERS. THE SNUBBERS ARE GRINNELL FIG. 200 HYDRAULIC SHOCK AND SWAY SUPPRESSORS.

NAME: STEVEN W. HARRIS

PHONE: EXT. 265



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920


BBS Ltr. #332-76

April 23, 1976

Mr. James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Enclosed please find Reportable Occurrence number 50-237/1976-15.
This report is being submitted to your office in accordance with the
Dresden Nuclear Power Station Technical Specifications, Section 6.6.B.


B. B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS:smp

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

4257