

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) SAN ONOFRE NUCLEAR GENERATING STATION, UNIT 3										DOCKET NUMBER (2) 0 5 0 0 0 3 6 2				PAGE (3) 1 OF 0 1		
TITLE (4) MISSED IODINE AND PARTICULATE SAMPLE																
EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)							
MONTH	DAY	YEAR	YEAR	SEQ. NUMBER	REV. NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)			
0 6	1 2	8 4	8 4	0 2 7	0 0	0 7	1 2	8 4					0 5 0 0 0			
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)														
4		20.402(b)				20.405(c)				50.73(a)(2)(iv)				73.71(b)		
POWER LEVEL (10)		20.405(a)(1)(i)				50.36(c)(1)				50.73(a)(2)(v)				73.71(c)		
0 0 0		20.405(a)(1)(ii)				50.36(c)(2)				50.73(a)(2)(vii)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)		
		20.405(a)(1)(iii)				X 50.73(a)(2)(i)				50.73(a)(2)(viii)(A)						
		20.405(a)(1)(iv)				50.73(a)(2)(ii)				50.73(a)(2)(viii)(B)						
		20.405(a)(1)(v)				50.73(a)(2)(iii)				50.73(a)(2)(x)						
LICENSEE CONTACT FOR THIS LER (12)																
NAME J. G. HAYNES, STATION MANAGER										TELEPHONE NUMBER AREA CODE 7 1 4 4 9 2 - 7 7 0 0						
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC						
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE)					X NO											

Abstract (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 6/12/84, with Unit 3 in Mode 4, daily containment airborne particulate and iodine samples were required to be taken from Radiation Monitor 3RT-7804 (EIS Component Code RIT) in accordance with Surveillance Requirement 4.11.2.1.2 following the reactor trip that occurred at 1818 on 6/11/84. A sample was taken at 2200 on 6/11/84 and 1900 on 6/13/84. The daily sample required on 6/12/84 was not taken.

The missed sample was due to an oversight by the responsible Chemistry Technician. The Chemistry Technician has been counseled on the importance of Technical Specification sampling requirements and appropriate disciplinary action has been taken. A memorandum was issued to all Unit 2/3 Chemistry Technicians requiring a review of specified procedures related to this occurrence. Completion of this review was verified by the Chemistry Technicians' initials. This is considered an isolated occurrence and no further corrective action is planned.

There are no credible circumstances that would have increased the severity of this event.

8407190482 840712
PDR ADOCK 05000362
S PDR

Southern California Edison Company



SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

J. G. HAYNES
STATION MANAGER

TELEPHONE
(714) 492-7700

July 12, 1984

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Docket No. 50-362
30-Day Report
Licensee Event Report No. 84-027
San Onofre Nuclear Generating Station, Unit 3

Pursuant to 10 CFR 50.73(a)(2)(i), this submittal provides the required 30-day written Licensee Event Report (LER) for an occurrence involving the Containment Airborne Radiation Monitoring System. Neither the health and safety of plant personnel nor the public were affected by this event.

If you require any additional information, please so advise.

Sincerely,

J. G. Haynes/sen

Enclosure LER No. 84-027

cc: A. E. Chaffee (USNRC Resident Inspector, Units 1, 2 and 3)
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

J. B. Martin (Regional Administrator, NRC Region V)

Institute of Nuclear Power Operations (INPO)

*IE22
1/1*