



Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429

July 12, 1984

FILE: B09-13510C
SERIAL: BSEP/84-1626

NRC Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20535

BRUNSWICK STEAM ELECTRIC PLANT UNIT 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
LICENSEE EVENT REPORT 1-84-9

Gentlemen:

On June 13, 1984, it was determined that actions performed on June 1, 1984, when the Unit 1 Core Spray System pumps' minimum flow valves, 1-E21-F031A and B, were declared inoperable and were closed and deenergized, resulted in increased potential of core spray pump inoperability during pump operation due to insufficient pump minimum flow protection. IER 1-84-9 was to have been submitted to your office by July 13, 1984. However, investigation and evaluation of this event is not yet complete. It is anticipated that this report will be submitted by July 27, 1984.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

MJP/k1b/LETKB1

Enclosure

cc: Mr. J. P. O'Reilly

8407200129 840712
PDR ADOCK 05000325
S PDR

IER 22
1/1