

LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M I D C C 1 2 0 0 - 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
01 REPORT SOURCE L 6 0 15 0 0 0 3 1 5 7 0 6 1 2 8 3 8 0 6 2 4 8 3 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 THE PERFORMANCE OF TRAIN B OF THE BORON INJECTION TANK INLET PIPING HEAT TRACE
03 CIRCUITRY WAS QUESTIONED ON 6/12/83 DURING THE SCHEDULED SURVEILLANCE TEST, BUT
04 THE TRAIN WAS NOT DECLARED INOPERABLE UNTIL 6/16/83. THE ACTION STATEMENT OF
05 T.S. 3.5.4.2 WAS NOT PERFORMED DURING THE PERIOD OF JUNE 12 TO JUNE 16. THE HEALTH
06 AND SAFETY OF THE PUBLIC WERE NOT AFFECTED.

07
08

09
SYSTEM CODE S F 11 CAUSE CODE D 12 CAUSE SUBCODE Z 13 COMPONENT CODE H E A T E R 14
COMP SUBCODE Z 15 VALVE SUBCODE Z 16
17 LER/RO REPORT NUMBER 8 3 11 EVENT YEAR 8 3 22 SEQUENTIAL REPORT NO. 0 5 3 24
OCCURRENCE CODE 0 1 28 REPORT TYPE T 30 REVISION NO. 0 32
ACTION TAKEN B 18 G 19 FUTURE ACTION Z 20 EFFECT ON PLANT Z 21 SHUTDOWN METHOD Z 21
HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NPRD-4 FORM SUB N 24 PRIME COMP. SUPPLIER L 25
COMPONENT MANUFACTURER C 3 3 2 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 MAINTENANCE REPAIRED A LOOSE SPLICE IN THE HEAT TRACE LINE ON 6/16/83. INVESTIGATION
11 ON THE MISSED SURVEILLANCE REQUIREMENTS IS CONTINUING. PROCEDURE CHANGES HAVE BEEN
12 MADE TO CORRECT A POSSIBLE CAUSE OF THIS EVENT. PERSONNEL CRUCIAL TO THE
13 INVESTIGATION WILL NOT BE AVAILABLE UNTIL AFTER 14 DAY REPORTING REQUIREMENT
14 L (EXPIRES 6/28/83). AN UPDATED LER WILL BE SUBMITTED.

15 FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31
DISCOVERY DESCRIPTION OPERATOR OBSERVATION 32
16 ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
PUBLCITY ISSUED N 44 DESCRIPTION NA 45
NRC USE ONLY

NAME OF PREPARER D. F. KRAUSE

PHONE (616) 465-5901

8307050019 830624
PDR ADOCK 05000315
S PDR



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

June 24, 1983

Mr. J.G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137


Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications
the following report/s are submitted:

RO 83-053/01T-0

Sincerely,


W.G. Smith, Jr.
Plant Manager

/bab

cc: J.E. Dolan
M.P. Alexich
R.F. Kroeger
B. Germano
E. Swanson/N. DuBry RO:III
R.C. Callen MPSC
G. Charnoff, Esq.
J.M. Hennigan
R.O. Bruggee EPRI
INPO
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (40 copies)
Dir., MIPC (4 copies)

JUN 27 1983

Handwritten initials/signature