



Commonwealth Edison

One First National Plaza, Chicago, Illinois

Address Reply to: Post Office Box 767

Chicago, Illinois 60690

JMB

May 18, 1984

Mr. James G. Keppler
Regional Administrator
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Byron Generating Station Units 1 and 2
Braidwood Generating Station Units 1 and 2
Pacific Air Products Linear Torque Converters
NRC Docket Nos. 50-454, 50-455, 50-456, & 50-457

Reference (a): March 28, 1984 letter from T. R. Tramm to
J. G. Keppler.

Dear Mr. Keppler:

This is to provide a second interim report on the 50.55(e) deficiency reported in reference (a) regarding linear torque converters in HVAC damper actuators. This deficiency is numbered 84-01 for Byron and 84-03 for Braidwood.

In reference (a) we indicated that a final report on PAPCO's evaluation of the discrepancy and on our refurbishing efforts would be available by May 28, 1984. At present PAPCO has submitted their report but the refurbishing is still in progress. Our final report will be submitted within sixty days.

If you have any questions regarding this matter please contact this office.

Very truly yours,

T. R. Tramm

T. R. Tramm

lm

cc: Director of Inspection & Enforcement
Resident Inspector - Byron
Resident Inspector - Braidwood

866GN

8405290300 840518
PDR ADOCK 05000454
S PDR

MAY 22 1984

IE27
1/0