



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

DMB

May 21, 1984

Mr. James G. Keppler
Regional Administrator
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Braidwood Station Units 1 and 2
10 CFR 50.55(e) Interim Report
L. K. Comstock Documentation Review
NRC Docket Nos. 50-456/457

Reference (a): E. D. Swartz letter to J. G. Keppler
dated March 2, 1984

Dear Mr. Keppler:

Reference (a) provided the thirty day 10 CFR 50.55(e) Report Number 84-01 concerning the subject documentation deficiencies at L. K. Comstock. In that report, we indicated our expectations for reconciliation of the inspection records by May 1, 1984 and subsequent issuance of the final report. The purpose of this letter is to provide the Region with an update in this matter.

Completion of the L. K. Comstock reconciliation of inspection records is now expected by early June, 1984. To date, however, no significant deficiencies requiring extensive rework have been identified. We expect to provide a report by the end of June 1984 detailing our assessment of this matter including identification of any resultant backlog of required Quality Control inspections for installed items.

Please address any questions that you or your staff may have concerning this matter to this office.

Very truly yours,

E. Douglas Swartz
Nuclear Licensing Administrator

cc: Director of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

RIII Inspector - Braidwood

8689N

8405300019 840521
PDR ADOCK 05000456
S PDR

MAY 24 1984

IE27
1/0