



**GPU Nuclear Corporation**

Post Office Box 388  
Route 9 South  
Forked River, New Jersey 08731-0388  
609 971-4000  
Writer's Direct Dial Number:

June 1, 1984

Mr. Darrell G. Eisenhut, Director  
Division of Licensing  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Dear Mr. Eisenhut:


Subject: Oyster Creek Nuclear Generating Station  
Docket No. 50-219  
Response to Generic Letter 84-11 - Inspections  
of BWR Stainless Steel Piping

The recent detection of flaws in Isolation Condenser System piping at Oyster Creek has introduced a delay in providing the forty-five (45) day response to Generic Letter 84-11.

It has just been determined that twenty-seven (27) Isolation Condenser System welds outside of containment possess crack-like ultrasonic indications. Because personnel that would ordinarily respond to Generic Letter 84-11 are deeply involved in the current problem, a realistic schedule for providing the required information would allow for a submittal on or about July 15, 1984.

In the event that any comments or questions arise, please contact Mr. Drew Holland at (609) 971-4643.

Very truly yours,

  
Peter B. Fiedler  
Vice President & Director  
Oyster Creek

PBF:DGH:dam

cc: Dr. Thomas E. Murley, Administrator  
Region I  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

NRC Resident Inspector  
Oyster Creek Nuclear Generating Station  
Forked River, NJ 08731

8406070794 840601  
PDR ADOCK 05000219  
Q PDR

*A001*  
*1/0*