



Northwestern Steel and Wire Company

121 WALLACE STREET • STERLING, ILLINOIS 61081

Telephone 815/625-2500 • TWX 910-642-3894

May 15, 1984

Mr. Thomas Tamble
Office of Inspection and Enforcement
U.S. NUCLEAR REGULATORY COMMISSION
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

CERTIFIED MAIL
-Return Receipt Requested

Dear Mr. Tamble:

As per our phone conversation of May 14, 1984, the following information is being sent to your office. This was received May 14, 1984, from Daniel International Corporation.

"Dear Sir:

Pursuant to our responsibilities as specified in Title 10 Code of Federal Regulations, Part 21 (10 CFR Part 21) Daniel International Corporation (DIC) wishes to advise you that material supplied by your company may be defective in workmanship. On December 30, 1983, Region IV of the NRC was advised of the conditions described in this letter by the owner of Wolf Creek Generating Station, Kansas Gas & Electric Company."

To date have requested samples which will be inspected either by an AISC representative or a Professional engineering firm. Further results will be forwarded to your office.

Respectfully,

NORTHWESTERN STEEL AND WIRE COMPANY

C. R. Wise

C. R. Wise
Supt. of Inspection & Quality Assurance

CRW:dmf

CC:

E. E. Shultz - V.P. of Operations
R. O. Hoeg - Asst. V.P. of Operations
G. T. Shinville - Gen. Supt. of Metallurgy & Inspection

8406120411 840515
PDR ADOCK 05000482
S PDR

MAY 16 1984 11/0
1517