



Boston Edison

Pilgrim Nuclear Power Station
Rocky Hill Road
Plymouth, Massachusetts 02360

10 CFR 50.73

E. T. Boulette, PhD

Senior Vice President — Nuclear

September 5, 1995

BECo Ltr. #95- 092

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

Docket No. 50-293
License No. DPR-35

The enclosed Licensee Event Report (LER) 95-007-00, "Simulated Automatic Actuation Test not Performed for the Automatic Depressurization System Prior to Plant Restart from Refuel Outage-10", is submitted in accordance with 10 CFR Part 50.73.

Within this report, the following commitment is made.

- The procedure governing the Master Surveillance Tracking Program will be revised to provide enhanced guidance to reviewers of changes/revisions to the Master Surveillance Tracking Program.

Please do not hesitate to contact me if there are any questions regarding this report.

E.T. Boulette, PhD

RLC/laa/9500700

cc: Mr. Thomas T. Martin
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Sr. NRC Resident Inspector - Pilgrim Station

Standard BECo LER Distribution

9509120231 950905
PDR ADOCK 05000293
S PDR

110080

JE22