




GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

June 19, 1984
RBG-18069
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Final Report/DR-162

Gulf States Utilities Company has completed its evaluation of DR-162 concerning nuisance tripping of A80L10 trip coils supplied by Gould and has determined that the trip coil setting information for Motor Control Center setpoint data did not reflect the +/- 20 percent manufacturing tolerances. The setpoint data has been appropriately revised. Because no deficiency exists, this condition does not meet the reporting requirements of 10CFR 50.55(e).

Sincerely,

J. E. Booker

J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JEB/PJD/lp

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

8406280137 840619
PDR ADOCK 05000458
S PDR

1527 1/0