

RECEIVED  
NRC

## Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

1984 JUN 21 PM 12:35

June 19, 1984  
G01-84-0184

REGION V

50-513

Mr. J. B. Martin  
Regional Administration  
Nuclear Regulatory Commission  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, Calif. 94596

Subject: NUCLEAR PROJECT NO. 4  
DOCKET NO. 50-513 REPORTABLE 10CFR50.55(e)  
ROCKBESTOS CABLE


Reference: 1) Telecon ME Rodin, Supply System to PP Narbut, Region V, Nuclear  
Regulatory Commission, dated 1/26/82  
2) G01-82-0060, dated 2/26/82, DW Mazur to RH Faulkenberry  
3) G01-82-0152, dated 4/21/82, RW Root to RH Faulkenberry  
4) G01-82-0413, dated 7/2/82, DW Mazur to RH Faulkenberry  
5) G01-83-344, dated 6/29/83, RA De Lorenzo to DM Sternberg

Reference 3) informed your office of a reportable deficiency under 10CFR50.55(e)  
and transmitted an interim status report on the subject condition.

Reference 4) provided the Supply System's final report on the above caption  
condition; however, a completion schedule had not yet been established. Since  
it has been determined that the only cable involved is that used in the Unit 4  
penetrations (see reference 4) this letter only refers to Unit 4 and Docket No.  
50-513.

During contract closeout activities, it was agreed between the Supply System and  
Westinghouse that the WNP-4 penetrations would be destroyed or made non-  
reusable. Therefore, sections of the defective cable were removed and the  
penetrations have been scrapped.

In view of this action, we consider the activities associated with this  
10CFR50.55(e) to be complete and will not submit any further reports.



R. W. Root, Director  
WNP-1/4 Program (821)

RWR.GAB:pp

cc: TA Mangelsdorf, BPC (862)  
V Mani, UE&C (897)  
EC Haren, UE&C (895)  
NRC Doc. Control Desk, DC  
FDCC (899)  
BDCC (828)  
ORM (847)

8406290280 840619  
PDR ADDCK 05000513  
S PDR

FILE COPY

IE-27 1/0