




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET • P.O. BOX 8008
NEW ORLEANS, LOUISIANA 70174-8008 • (504) 388-2345

September 18, 1984

W3P84-2583
Q-3-A35.07.57
3-A1.01.04



Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

REFERENCE: 1) LP&L letter W3K84-1218 dated May 22, 1984
2) NRR letter dated June 13, 1984 from Darrell G. Eisenhower to J.M. Cain

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Reopening of Significant Construction Deficiency No. 57
"Inadequate Instrumentation and Control Installations Turnover Documentation"

Because of ongoing efforts associated with resolution of issues in reference 2, it may be necessary to modify reference 1. We therefore have elected to reopen SCD57 pending completion of those efforts. A final report will be issued upon completion of this effort which is currently scheduled for October 5, 1984.

Very truly yours,

K.W. Cook
Nuclear Support & Licensing Manager

KWC/RJB/ss

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8410100319 840918
PDR ADOCK 05000282
S PDR

IE-27

1/0

Mr. John T. Collins

W3P84-2583

Page 2

cc: Mr. E. L. Blake

Shaw, Pittman, Potts & Trowbridge

1800 M. Street, N.W.

Washington, D.C. 20036

Mr. W. M. Stevenson

Monroe & Lemann

1424 Whitney Building

New Orleans, Louisiana 70130

Mr. W. A. Cross

7910 Woodmont Avenue

Suite 1200

Bethesda, Maryland 20814