

LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
NEW ORLEANS, LOUISIANA


P.O. BOX 8008
70174-8008

(504) 368-2345

September 21, 1984

W3P84-2656
Q-3-A35.07.60
3-A1.01.04

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



REFERENCE: LP&L letter W3K84-2053 dated August 31, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 60
"Turnover Documentation and Inadequate Hanger
Weld Problems T&B"
Twelfth Interim Report

The above referenced letter indicated submittal of the Final Report to the NRC on September 21, 1984.

At the present time, the evaluation of the walkdown results is considered complete and Inspection Report 84-30, performed by the Construction Appraisal Team (CAT), indicated this item as closed. However, package assemblance and final review is underway with a scheduled completion of mid October.

A final report is scheduled for transmittal to the NRC by October 22, 1984.

Very truly yours,

K.W. Cook
Nuclear Support & Licensing Manager

KWC/RJB/ss

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8410100764 840921
PDR ADDCK 05000382
S PDR

IE-27,10

• Mr. J.T. Collins
W3P84-02656
Page 2

cc: Mr. E.L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M. St. N.W.
Washington, D.C. 20036

Mr. W.M. Stevenson
Monroe & Lemann
1424 Whitney Bldg.
New Orleans, LA 70130

Mr. W.A. Cross
4827 Rugby Ave.
Suite B-1
Bethesda, MD 20814