


LOUISIANA
POWER & LIGHT

142 DELARONDE STREET • P.O. BOX 8008
NEW ORLEANS, LOUISIANA 70174-8008 • (504) 366-2345

September 21, 1984

W3P84-2673
Q-3-A35.07.90
3-A1.01.04

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



REFERENCE: LP&L letter W3K84-2036 dated August 30, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No.3
Docket No. 50-382
Significant Construction Deficiency No. 90
"Electrical Conduit Overstressed"
Sixth Interim Report

The above referenced letter indicated submittal of the Final Report to the NRC on September 21, 1984.

At the present time, approximately one thousand additional conduits were identified as requiring reinspection. Walkdowns, evaluation, & rework are estimated to be completed by mid October. The final report is scheduled to be submitted to the NRC by October 26, 1984.

Very truly yours,

K.W. Cook
Nuclear Support & Licensing Manager

KWC/RJB/ss

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

IE-27 1/0

8410110042 840921
PDR ADDCK 05000382
S PDR

Mr. John T. Collins
W3P84-2673
Page 2

cc: Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M. Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Mr. W. A. Cross
4827 Rugby Avenue
Suite B-1
Bethesda, Maryland 20814