


LOUISIANA
POWER & LIGHT

142 DELARONDE STREET • P.O. BOX 8008
NEW ORLEANS, LOUISIANA 70174-8008 • (504) 386-2345

September 21, 1984

W3P84-2647
Q-3-A35.07.78
3-A1.01.04

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



REFERENCE: LP&L letter W3K84-2034 dated August 30, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 78
"American Bridge Structural Steel Deficiencies"
Thirteenth Interim Report

The above referenced letter indicated submittal of the final report on SCD-78 to the NRC on September 21, 1984.

At the present time, corrective action and documentation reviews are re-scheduled to be completed in early October and the final report is scheduled to be submitted to the NRC by October 30, 1984.

Very truly yours,

K.W. Cook
Nuclear Support & Licensing Manager

KWC/GEW/ss

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

15427 1/0

8410110137 840921
PDR ADOCK 05000382
S PDR

Mr. John T. Collins
W3P84-2647
Page 2

cc: Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M. Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Mr. W. A. Cross
4827 Rugby Avenue
Suite B-1
Bethesda, Maryland 20814