

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)

Vermont Yankee Nuclear Power Station

DOCKET NUMBER (2)

0 5 0 0 0 2 7 1 1

PAGE (3)

1 OF 0 2

TITLE (4)

Environmental Sampling Station Inoperable

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0 6	1 7	8 4	8 4	0 0 8	0 0	0 7	1 2	8 4			0 5 0 0 0

OPERATING MODE (5)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)										
POWER LEVEL (10)	0 9 2	20.402(b)			20.405(a)			50.73(a)(2)(iv)			73.71(b)	
		20.405(a)(1)(i)			50.38(a)(1)			50.73(a)(2)(v)			73.71(e)	
		20.405(a)(1)(ii)			50.38(a)(2)			50.73(a)(2)(vi)			OTHER (Specify in Abstract below and in Text, NRC Form 365A)	
		20.405(a)(1)(iii)			50.73(a)(2)(i)			50.73(a)(2)(viii)(A)				
		20.405(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(viii)(B)				
20.405(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(x)						

LICENSEE CONTACT FOR THIS LER (12)

NAME				TELEPHONE NUMBER			
				AREA CODE			

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)		NO		EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR
<input checked="" type="checkbox"/>		<input type="checkbox"/>						

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

For the period 6/12/84 to 6/17/84 weekly air particulate and charcoal cartridge sampling was not performed as required by Tech. Spec. section 4.9.D.2 and table 3.9.1. The air sampling station in North Hinsdale, NH was left off by a technician performing required environmental radiation surveillance.

In order to reduce the chance of a similar event, plant procedures have been revised to require that the technician initials the sample envelope upon insuring the system is operable after sample data is collected. All technicians involved in the use of the revised procedure will be notified of the changes to the procedure and instructed on the proper performance on all new requirements.

8407170348 840712  
PDR ADOCK 05000271  
S PDR

IE22  
11

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)  Vermont Yankee	DOCKET NUMBER (2)  0 5 0 0 0 2 7 1	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 4	— 0 0 8	— 0 0 0	2	OF	0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)


For the period 6/12/84 to 6/17/84 weekly air particulate and charcoal cartridge sampling was not performed as required by Tech. Spec. section 4.9.D.2 and table 3.9.1. The air sampling station in North Hinsdale, NH was left off by a technician performing required environmental radiation surveillance.

The technician, prior to leaving the sampling station, should have insured that flow was established by the developed vacuum in the suction tube and noted this on the sample envelope. In this case the technician did not check the sampler suction tubing and the fact that the station was off was not discovered.

The VY procedure used by the technician has been revised to require the technician to initial the sample envelope after noting the results of the vacuum check. Also, all of the technicians involved with performance of this procedure will be notified of the changes and instructed on the proper performance of the new requirements that resulted due to this event.

A review of the weeks prior to and following the missed analysis did not reveal any reason to suspect other than normal readings.

Based on the above there were no adverse effects on the public health and safety. A similar occurrence was reported as LER 79-19.



# VERMONT YANKEE NUCLEAR POWER CORPORATION

P. O. BOX 157  
GOVERNOR HUNT ROAD  
VERNON, VERMONT 05354  
VYV84-367

July 12, 1984


U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

REFERENCE: Operating License DPR-28  
Docket No. 50-271  
Reportable Occurrence No. LER 84-08

Dear Sirs:

As defined by 10CFR50.73, we are reporting the attached Reportable Occurrence as LER 84-08.

Very truly yours,

  
James P. Pelletier  
Plant Manager

RDP/cjm

cc: Regional Administrator  
USNRC Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

IE22  
11