

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Vermont Yankee Nuclear Power Station										DOCKET NUMBER (2) 0 5 0 0 0 2 7 1 1										PAGE (3) 1 OF 0 2																																	
TITLE (4) 1984 Type C Testing																																																					
EVENT DATE (5)										LER NUMBER (6)										REPORT DATE (7)										OTHER FACILITIES INVOLVED (8)																							
MONTH			DAY			YEAR				YEAR			SEQUENTIAL NUMBER			REVISION NUMBER				MONTH			DAY			YEAR				FACILITY NAMES										DOCKET NUMBER(S)													
0 6			1 6			8 4				8 4			0 1			1 0				0 0			0 7			1 6				8 4														0 5 0 0 0 0									
0 6			1 6			8 4				8 4			0 1			1 0				0 0			0 7			1 6				8 4														0 5 0 0 0 0									
OPERATING MODE (9) N										THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																																											
POWER LEVEL (10) 0 1 0 0										20.402(b)										20.405(c)										50.73(a)(2)(iv)										73.71(b)													
										20.405(a)(1)(i)										50.36(e)(1)										50.73(a)(2)(v)										73.71(e)													
										20.405(a)(1)(ii)										50.36(e)(2)										50.73(a)(2)(vii)										OTHER (Specify in Abstract below and in Text, NRC Form 366A)													
										20.405(a)(1)(iii)										X 50.73(a)(2)(i)										50.73(a)(2)(viii)(A)																							
										20.405(a)(1)(iv)										50.73(a)(2)(ii)										50.73(a)(2)(viii)(B)																							
										20.405(a)(1)(v)										50.73(a)(2)(iii)										50.73(a)(2)(ix)																							
LICENSEE CONTACT FOR THIS LER (12)																																																					
NAME James P. Pelletier, Plant Manager																				TELEPHONE NUMBER																																	
																				AREA CODE 8 0 2 2 5 7 - 7 7 1 1																																	
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																																																					
CAUSE			SYSTEM			COMPONENT			MANUFACTURER			REPORTABLE TO NPROS			CAUSE			SYSTEM			COMPONENT			MANUFACTURER			REPORTABLE TO NPROS																										
X			S B			V R			3 4 0			Y			X			B B			V A			1 8 0			Y																										
X			A A			V C			6 3 1			Y			B			S J			V A			3 9 1			Y																										
SUPPLEMENTAL REPORT EXPECTED (14)																				EXPECTED SUBMISSION DATE (15)										MONTH DAY YEAR																							
YES (If yes, complete EXPECTED SUBMISSION DATE)																				X NO																																	

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

While performing Type C Leak Rate Testing MSIV-86B, CRD-412A, PCAC V16-19-8 and FDW-96A were found to have seat leakage in excess of that permitted by Tech. Spec. Section 3.7.A.4.

Vermont Yankee will perform maintenance on all of the above valves and retest them to insure that seat leakage is within Tech. Spec. allowables prior to plant startup following the 1984 refueling outage.

8407230034 840716
PDR ADOCK 05000271
S PDR

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES 9/31/85

FACILITY NAME (1) Vermont Yankee	DOCKET NUMBER (2) 0 5 0 0 0 2 7 1 8 4 - 0 1 1 - 0 0 0 2 OF 0 2	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			

TEXT (If more space is required, use additional NRC Form 365A's) (17)

While performing Type C Leak Rate Testing, MSIV-86B, CRD-412A, PCAC V16-19-8 and FDW-96A were found to have seat leakage in excess of that permitted by Tech. Spec. section 3.7.A.4.

For MSIV-86B, CRD-412A and PCAC V16-19-8, a second isolation valve, in the applicable system, was tested and met the acceptance criteria. For FDW-96A, containment was provided by the water seal on the inboard check valve and the plant's capability to maintain a pressure greater than P_a on the feedwater system.

Vermont Yankee will perform maintenance on all of the above valves and re-test them to insure that seat leakage is within Tech.Spec. allowables prior to Plant startup.

No similar events have been reported on MSIV-86B, CRD-412A or PCAC V16-19-8 in the last five years.

A similar event was reported on FDW-96A as LER 83-10.



VERMONT YANKEE NUCLEAR POWER CORPORATION

P. O. BOX 157
GOVERNOR HUNT ROAD
VERNON, VERMONT 05354

July 16, 1984

VYV84-370

U. S. Nuclear Regulatory Commission
Document No. 50-271
Washington, D. C. 20555

REFERENCE: Operating License DPR-28
Docket No. 50-271
Reportable Occurrence No. LER 84-11

Dear Sirs:

As defined by 10CFR50.73, we are reporting the attached Reportable Occurrence as LER 84-11.

Very truly yours,

James P. Pelletier
Plant Manager

RDP/cjm

cc: Regional Administrator
USNRC Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

IE22
11