



## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Sequoyah, Unit 1	0 5 0 0 0 3 2 7 8 4	—	0 5 3	—	0 0	0 2	OF 0 2

TEXT (If more space is required, use additional NRC Form 365A's) (17)

With unit 1 at 100 percent power and unit 2 in mode 3, hot standby, both trains at the auxiliary building gas treatment system were declared inoperable due to an uncontrolled breach of the ABSCE boundary. During a routine safety inspection of the auxiliary building and west valve room for unit 1 the inner door was noted to have been breached using the proper administrative controls, however, the outer door was inadvertently left ajar allowing a breach of the ABSCE boundary.

Immediately upon discovery of the event the outer door was closed and the control room notified of the noncompliance. Operations personnel verified that the door was closed and the ABSCE and ARGTS declared operable. A major contributing factor to this breach was the failure of procedures to identify and post doors which are part of ABSCE boundary.

Corrective actions taken and planned to prevent further recurrence are:

1. Plant procedure TI-77 has been revised to list all doors which are part of the ABSCE boundary.
2. A night order was issued by Operations supervisor to require all auxiliary building door breaches to be evaluated by the shift engineer.
3. All ABSCE boundary doors will be appropriately labeled.

A safety assessment was performed and there was no effect upon public health and safety.

TENNESSEE VALLEY AUTHORITY

Sequoyah Nuclear Plant  
Post Office Box 2000  
Soddy Daisy, Tennessee 37379

October 2, 1984

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555


Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET NO.  
50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE REPORT  
SQRO-50-327/84053

The enclosed licensee event report provides details concerning the breach of Auxiliary Building Secondary Containment Enclosure on September 5, 1984. This event is reported in accordance with 10 CFR 50.73, paragraph a(2)vii.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



P. R. Wallace  
Plant Manager

Enclosure  
cc (Enclosure):

James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Suite 2900  
101 Marietta Street, NW  
Atlanta, Georgia 30323

Records Center  
Institute of Nuclear Power Operations  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339

NRC Inspector, NUC PR, Sequoyah

IE21  
11