

Bechtel Power Corporation

Engineers - Constructors

12400 East Imperial Highway

Norwalk, California 90650

MAIL ADDRESS


P.O. BOX 60860 - TERMINAL ANNEX, LOS ANGELES, CALIFORNIA 90060

TELEPHONE: (213) 807-2000

September 26, 1984



Mr. J. T. Collins
Regional Administrator, Region IV
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



Subject: Rear Bracket to Snubber Interference

Reference: Final 10CFR50.55(e) Report to J. T. Collins from
G. W. Oprea, Jr., Executive Vice President,
Houston Lighting and Power

Dear Mr. Collins:

On August 23, 1984, Mr. Oprea informed the Nuclear Regulatory Commission Region IV of the subject deficiency pursuant to the requirements of 10CFR50.55(e).

Subsequent evaluation by the Bechtel Review Committee concluded that the condition is reportable also under 10CFR21. The reference report contains all the information required by Part 21 with the exception of the information required by 21.21(b)(3) as it is known to Bechtel.

NPS Industries was advised of the Bechtel evaluation and will be further advised by a copy of this letter.

Sincerely,

BECHTEL POWER CORPORATION
Western Power Division

for *R. J. Loutch*
E. R. Nelsen
Manager of Division Quality Assurance

ERN/AGC:dmb

8410150482 840926
PDR ADOCK 05000498
S PDR

IE-27
1/0