

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

34 JUL 23, 1984 12


Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Re: Catawba Nuclear Station
Units 1 and 2
Docket Nos. 50-413 and 50-414
Significant Deficiency No. 413-414/83-17
Special Weld Boss Restrictor Applications

Dear Mr. O'Reilly:

My letter of March 29, 1984 stated that all corrective action for Unit 2 concerning the subject deficiency would be complete by June 30, 1984. In our investigation, we found 8 locations of the 70 restrictor locations, to be overdrilled, 2 applications that require further evaluation and 2 that are not yet installed. Due to the required rework for these situations, additional time is needed to clear this deficiency. This work should be completed by August 24, 1984.

Very truly yours,



Hal B. Tucker

LTP/rhs

Attachment

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector
Catawba Nuclear Station

Palmetto Alliance
2135 1/2 Devine Street
Columbia, South Carolina 29205

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

Mr. Robert Guild, Esq.
Attorney-at-Law
P. O. Box 12097
Charleston, South Carolina 29412

Mr. Jesse L. Riley
Carolina Environmental Study Group
854 Henley Place
Charlotte, North Carolina 28207

8407250356 840703
PDR ADOCK 05000413
S PDR

ORIGINAL COPY

TE 27/10