

**CP&L**

Carolina Power &amp; Light Company

~~84 JUL 11 9:16~~  
Brunswick Steam Electric Plant  
P. O. Box 10429  
Southport, NC 28461-0429

July 9, 1984

FILE: B09-13510C  
SERIAL: BSEP/84-1596


Mr. James P. O'Reilly, Administrator  
U. S. Nuclear Regulatory Commission  
Suite 2900  
101 Marietta Street N.W.  
Atlanta, GA 30323

BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2  
DOCKET NO. 50-324  
LICENSE NO. DPR-62  
SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8 AND  
PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (2-SR-84-9)

Dear Mr. O'Reilly:

During an ongoing Unit 2 refueling/maintenance outage, a Unit 2 fire barrier LCO was initiated on June 2, 1984, for a fire door in the Unit 2 Reactor Building. Door No. 303, located on the 50-foot elevation of the building, provides personnel access to the Reactor Building from the roof area of the Unit 2 Turbine Building. The subject LCO was initiated to permit repair of the door, which would not open properly when using the door security card reader. Required repairs to the door were completed, and the door was returned to service on June 10, 1984. During the time period the subject LCO was in effect, appropriate fire watches were maintained.

Very truly yours,



C. R. Dietz, General Manager  
Brunswick Steam Electric Plant

MJP/jlh/LETJH1

Enclosure

cc: Mr. R. C. DeYoung  
NRC Document Control Desk

8407250520 840709  
PDR ADOCK 05000324  
S PDR

OFFICIAL COPY

Te 27 1/0