




**LOUISIANA**  
POWER & LIGHT

WATERFORD 3 SES • P.O. BOX B • KILLONA, LA 70066

September 28 1984

W3P84- 2740  
Q-3-A35.07.108  
3-A1.01.04

Mr. John T. Collins  
Regional Administrator, Region IV  
U.S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76012



Dear Mr. Collins:

Subject: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 108  
"Potential Failure to Comply with FSAR Safe  
Shutdown Commitment" Fifth Interim Report

Reference: LP&L Letter W3K84-2547 dated September 14, 1984

The above referenced letter indicated submittal of the Final Report to the USNRC on September 28, 1984.

However, during validation of FP Control Room/Cable Vault Safe Shutdown List in the FSAR, seven (7) additional cables were identified which require re-routing from the cable vault. The final report is scheduled to be submitted to the NRC on October 31, 1984.

Very truly yours,

K.W. Cook  
Nuclear Support & Licensing Manager

KWC:RJB:pbs

cc: Director  
Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8410170031 840928  
PDR ADOCK 05000382  
S PDR

IE-27

1/0

Mr. John T. Collins  
W3P84- 2740  
Page 2

cc: Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. E. L. Blake  
Shaw, Pittman, Potts & Trowbridge  
1800 M. Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130

Mr. W. A. Cross  
4827 Rugby Avenue  
Suite B-1  
Bethesda, Maryland 20814

Mr. G. W. Knighton, Chief  
Licensing Branch, No. 3  
Division of Licensing  
Washington, D.C. 20555