



MIDDLE SOUTH
UTILITIES SYSTEM

LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
NEW ORLEANS, LOUISIANA


• P.O. BOX 8008
70174-8008

• (504) 386-2345

October 2, 1984

W3P84-2764
Q-3-A35.07.116
3-A1.01.04

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012



Dear Mr. Collins:

Subject: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 116
"Failure of Static Uninterruptible Power Supply (SUPS) Inverters"
Second Interim Report

Reference: LP&L letter W3K84-2013 dated August 28, 1984.

The referenced letter indicated submittal of the final report to the NRC on September 30, 1984. The test data is undergoing final review and setpoints/hardware changes may be necessary. A final report is rescheduled to be submitted to the NRC by October 30, 1984.

Very truly yours,

K.W. Cook
Nuclear Support & Licensing Manager

KWC/RJB/sms

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8410180497 841002
PDR ADOCK 05000382
S PDR

IE-27 1/0

Mr. John T. Collins

W3P84-2764

Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M. Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Mr. G. W. Knighton, Chief
Licensing Branch No. 3
Division of Licensing
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. W. A. Cross
4827 Rugby Avenue
Suite B-1
Bethesda, Maryland 20814