



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

84 OCT 10 P 1:07
October 5, 1984

NUCLEAR LICENSING & SAFETY DEPARTMENT

U.S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 2900
Atlanta, Georgia 30323

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1 and Unit 2
Docket No. 50-416 and 50-417
License No. NPF-13
File: 0260/L-835.0
PRD-84/06, Interim Report for
Unit 2, Potential Defect in
Spare Piston Skirt Casings
AECM-84/0464

Per the referenced letter, Mississippi Power & Light Company (MP&L) provided a 10CFR21 Report for Grand Gulf Nuclear Station (GGNS) Unit 1 and reported that reportability for Unit 2 was indeterminate at the time. The deficiency concerned improper heat treatment for certain spare TDI piston skirt casings. This letter provides a status update for the Unit 2 evaluation for reportability of this item under 10CFR50.55(e).

MP&L is currently awaiting outcome from the Transamerica Delaval, Inc. (TDI) Diesel Generator Owners Group concerning this problem and other problems related to TDI Diesel Generators. Reportability for GGNS Unit 2 is still indeterminate. MP&L expects to submit an update for Unit 2 by January 26, 1985.

Yours truly,

L. F. Dale
Director

EBS/SHH:rg

cc: Mr. J. B. Richard
Mr. R. B. McGehee
Mr. N. S. Reynolds
Mr. G. B. Taylor

Mr. Richard C. DeYoung, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Member Middle South Utilities System

8410190024 841005
PDR ADOCK 05000416
S PDR

OFFICIAL COPY

1/0
TE27